














 **SYNERGEE[®]**

ADJUSTABLE INCLINE DECLINE BENCH



PARTS LIST









IF ANY PIECES ARE MISSING, PLEASE CONTACT US IMMEDIATELY:
HELLO@SYNERGEEFITNESS.COM OR 1.855.217.7136

1.  94-02-01 QTY x1	2.  94-02-02 QTY x1	3.  94-02-03 QTY x1	4.  94-02-04 QTY x1	5.  94-02-05 QTY x1
6.  94-02-06 QTY x1	7.  94-02-07 QTY x1	8.  94-02-08 QTY x1	9.  94-02-09 QTY x2	10.  94-02-10 QTY x1
11.  94-02-11 QTY x2	12.  94-02-12 QTY x1	13.  94-02-13 QTY x2		




PARTS LIST

IF ANY PIECES ARE MISSING, PLEASE CONTACT US IMMEDIATELY:
HELLO@SYNERGEEFITNESS.COM OR 1.855.217.7136


A.  QTY x4 M8x16 FULLY THREADED BOLT	B.  QTY x8 M8x35 FULLY THREADED BOLT	C.  QTY x6 M10x55 PARTIALLY THREADED BOLT	D.  QTY x1 M12x110 PARTIALLY THREADED BOLT	E.  QTY x12 M8 WASHER
F.  QTY x12 M10 WASHER	G.  QTY x2 M12 WASHER	H.  QTY x6 M10 CAP NUT	I.  QTY x1 M12 NUT	

HARDWARE SIZING CHART


**M8x16
BOLT**




**M8x35
BOLT**



**M10x55
BOLT**



**M12x110
BOLT**




ASSEMBLY

STEP: 1

STEP PART GUIDE

#	PART NAME	QTY
1.	94-02-01	1
2.	94-02-02	1
3.	94-02-03	1
C.	M10X55 STEEL SQUARE-NECK CARRIAGE BOLTS	4
F.	M10 WASHER	8
G.	M10 CAP NUT	4




ASSEMBLY

STEP: 2

STEP PART GUIDE

#	PART NAME	QTY
8.	94-02-08	1
C.	M10X55 PARTIALLY THREADED BOLT	2
F.	M10 WASHER	4
H.	M10 CAP NUT	2




ASSEMBLY

STEP: 3

STEP PART GUIDE

#	PART NAME	QTY
7.	94-02-07	1
10.	94-02-10	1
B.	M8x35 FULLY THREADED BOLT	4
E.	M8 WASHER	4




ASSEMBLY

STEP: 4

STEP PART GUIDE

#	PART NAME	QTY
4.	94-02-04	1
5.	94-02-05	1
6.	94-02-06	1
A.	M8x16 FULLY THREADED BOLT	4
B.	M8x35 FULLY THREADED BOLT	4
F.	M10 WASHER	8





ASSEMBLY

STEP: 5-A

STEP PART GUIDE

#	PART NAME	QTY
-	ASSEMBLY FROM STEP 4	-





ASSEMBLY

STEP: 5-B

STEP PART GUIDE

#	PART NAME	QTY
-	ASSEMBLY FROM STEP 3	-
D.	M12x110 PARTIALLY THREADED BOLT	1
G.	M12 WASHER	2
I.	M12 NUT	1




ASSEMBLY

STEP: 6-A

STEP PART GUIDE

#	PART NAME	QTY
13.	94-02-13	1




ASSEMBLY

STEP: 6-B

STEP PART GUIDE

#	PART NAME	QTY
13.	94-02-13	1



ASSEMBLY

STEP: 7

STEP PART GUIDE

#	PART NAME	QTY
9.	94-02-09	2
11.	94-02-11	2
12.	94-02-12	1

